

MONSANTO PRODUCT NAME

## MCS-352 HYDRAULIC ASSEMBLY LUBRICANT

MONSANTO COMPANY  
800 N. LINDBERGH BLVD.  
ST. LOUIS, MO 63167

**Emergency Phone No.**  
**(Call Collect)**  
**314-694-1000**

### PRODUCT IDENTIFICATION

**CAS No.:** MCS-352 lubricant is a proprietary mixture of components. It has no CAS number. All components appear on the inventory of chemical substances published by the U.S. Environmental Protection Agency.

**Chemical Family:** Phosphate ester

**DOT Hazard Class:** Product is not classified as a hazardous material by the U.S. Department of Transportation.

**DOT Label Requirement:** Product Label

**Reportable Quantity (RQ)  
Under U.S. Clean Water  
Act Regulations:** Not Listed

### WARNING STATEMENTS

CAUTION!  
MAY CAUSE IRRITATION TO EYES AND SKIN

### PRECAUTIONARY MEASURES

Avoid prolonged or repeated skin contact. Wear impervious gloves.  
Do not get in eyes. Wear chemical safety goggles.

### EMERGENCY AND FIRST AID PROCEDURES

**FIRST AID:** IF IN EYES, immediately flush with plenty of water for at least 15 minutes. Call a physician.

IF ON SKIN, immediately flush with plenty of water. Wash skin thoroughly with soap and water. Remove contaminated clothing. Wash clothing before reuse.

### OCCUPATIONAL CONTROL PROCEDURES

**Eye Protection:** Wear chemical safety goggles to prevent eye contact.

**Skin Protection:** Wear protective gloves to minimize skin contact.

**Respiratory Protection:** Use NIOSH approved equipment with full facepiece when airborne exposure is excessive. Consult respirator manufacturer to determine appropriate type equipment for given application.

**Ventilation:** Provide ventilation to minimize exposure. Local exhaust ventilation preferred.

(Occupational Control Procedures Continued On Next Page)

MATERIAL SAFETY DATA

MCS-352 Hydraulic Assembly Lubricant

## OCCUPATIONAL CONTROL PROCEDURES (Continued)

**Airborne**

**Exposure Limits:** No permissible exposure limit or threshold limit value has been established by OSHA or the ACGIH for MCS-352 Hydraulic Assembly Lubricant.

Contains: Tributyl Phosphate (CAS No. 126-73-8)

OSHA PEL/TWA: 5 mg/m<sup>3</sup> (0.4 ppm)  
ACGIH TLV®/TWA: 2.5 mg/m<sup>3</sup> (0.2ppm)  
ACGIH TLV/STEL: 5 mg/m<sup>3</sup> (0.4 ppm)

## FIRE PROTECTION INFORMATION

**Flash Point:** >350°F **Method:** Cleveland Open Cup

**Extinguishing Media:** Dry powder, carbon dioxide, chemical foams, and water fog.

**Special Firefighting Procedures:** When fighting any chemical fire, firefighters should wear full protective clothing and self-contained breathing apparatus.

**Unusual Hazards:** Oxides of phosphorus may be produced in fires along with carbon monoxide (CO), carbon dioxide (CO<sub>2</sub>), soot, smoke, and hydrocarbons.

## REACTIVITY DATA

**Hazardous Decomposition Products:** Oxides of phosphorus may be produced in fires along with CO, CO<sub>2</sub>, soot, smoke, and hydrocarbons.

**Hazardous Polymerization:** Does not occur.

## PHYSIOLOGICAL EFFECTS SUMMARY

Oral LD<sub>50</sub> (Rat): 4,307 mg/kg, Slightly Toxic  
Dermal LD<sub>50</sub> (Rabbit) : >2,000 mg/kg, Slightly Toxic  
Eye Irritation (Rabbit) : (Avg. Max.) 2.6 on a scale of 110.0, Slightly Irritating  
Skin Irritation (Rabbit) : (Avg. Max.) 0.4 on a scale of 8.0, Practically Nonirritating  
Aerosol Inhalation (Rat) : 0 out of 10 rats died when exposed to nominal concentration of 4.15 mg/l air of a minor component of this material for 4 hours.

## PHYSICAL DATA

**Appearance:** Very viscous purple oil  
**Boiling Point @ 760 mm Hg:** 350°C (with decomposition)  
**Pour Point:** 20°F  
**Specific Gravity @ 25/25°C:** 1.02  
**Viscosity @ 210°F:** 190-225 centistokes

**Note:** These physical data are typical values based on material tested but may vary from sample to sample. Typical values should not be construed as a guaranteed analysis of any specific lot or as specification items.

## SPILL, LEAK & DISPOSAL INFORMATION

**Waste Disposal:** Waste product should be incinerated or disposed of in a hazardous waste landfill which complies with local, state, and federal regulations.

### **Spill or Leakage**

**Procedures:** Spills should be absorbed on a suitable medium such as sawdust, clay or filtercel.

This material should not be dumped, spilled, rinsed, or washed into sewers or public waterways.

**DATE:** 12/19/83

**REVISED:**

**SUPERSEDES:**

**MSDS NO.:** M00006601

FOR ADDITIONAL NON-EMERGENCY INFORMATION, CONTACT:

Monsanto Company  
800 N. Lindbergh Blvd.  
St. Louis, MO 63167  
314-694-1000

Although the information and recommendations set forth herein (hereinafter "Information") are presented in good faith and believed to be correct as of the date hereof, Monsanto Company makes no representations as to the completeness or accuracy thereof. Information is supplied upon the condition that the persons receiving same will make their own determination as to its suitability for their purposes prior to use. In no event will Monsanto Company be responsible for damages of any nature whatsoever resulting from the use of or reliance upon Information. NO REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS OR IMPLIED, OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR OF ANY OTHER NATURE ARE MADE HEREUNDER WITH RESPECT TO INFORMATION OR THE PRODUCT TO WHICH INFORMATION REFERS.

This form has been approved by the Occupational Safety and Health Administration as "equivalent to" OSHA Form 20.

TLV\* is a registered trademark of the American Conference of Governmental Industrial Hygienists. (ACGIH)

MATERIAL SAFETY DATA MCS-352 Hydraulic Assembly Lubricant